Facility: Grand Ave. (Downtown Optimist) Park

Address: 100 E. Forest Ave. Date of Survey: 05/31/10



1 ACCESS TO THE SITE AND/OR FACILITY

1.1 Exterior Accessible Route (sidewalks, paths, etc.)

Refer to site plan included with this report: (A) Install concrete access path from shelter to one BBQ grill w/ max. slope of 5% and max. cross-slope of 2% (B) Install concrete access path from shelter to basketball court w/ max. slope of 5% and max. cross-slope of 2% (C) Install concrete access path from existing sidewalk over to play area with swings.
Estimated Cost: \$3,481.00

1.2 Parking

No off-street parking is provided at this park site.

09/15/11 Page 1 of 8

1.3 Curb Cuts & Curb Ramps

Refer to site plan included with this report: (D) Replace existing curb-cut at E. Forest Ave. (see photo 1 below) with ADA compliant curb-cut w/ contrasting truncated dome detectable warning surface.
Estimated Cost: \$2,500.00



Photo 1

1.4 Exterior Ramps

• Refer to site plan included with this report: (E) Install a 6' long x 5' wide concrete ramp (no rails required) from existing sidewalk down into the playground area.

Estimated Cost: \$1,146.00

1.5 Exterior Stairs

None exist.

2 SERVICES

2.1 Building Entrances (exterior doors)

Not applicable.

2.2 Interior Accessible Route

Not applicable.

2.3 Interior Ramps

Not applicable.

09/15/11 Page 2 of 8

2.4 Interior Stairs

Not applicable.

2.5 Elevators

Not applicable.

2.6 Platform (wheelchair) Lifts

- None exist.
- 2.7 Doors (interior, excluding restroom doors addressed in 3.1 and non-public area doors)
 - Not applicable.
- 2.8 Places of Assembly (auditoriums, meeting rooms, gymnasiums, etc.)
 - Not applicable.

2.9 Seating and Tables

Add one wheelchair accessible picnic table at the shelter.

Estimated Cost: \$850.00

- 2.10 Restaurant (including dining areas, snack bars & public use kitchens)
 - Not applicable.
- **2.11 NOT USED**
- 2.12 Business and Mercantile
 - Not applicable.
- 2.13 Dressing and Fitting Rooms
 - Not applicable.
- **2.14 NOT USED**
- **2.15 NOT USED**
- 2.16 Libraries
 - Not applicable.

09/15/11 Page 3 of 8

2.17 Storage

Not applicable.

3 ACCESS TO PUBLIC AMENITIES

3.1 Drinking Fountains

No work.

3.2 Restrooms

None exist.

3.3 Signage

Not applicable.

3.4 Bathtub & Showers (including locker rooms and dressing rooms)

Not applicable.

4 BARRIER REMOVAL - OTHER

4.1 Alarms

Not applicable.

4.2 Public Telephones

None exist.

4.3 Protruding Objects

None exist.

4.4 Playgrounds

Supplement and compact the wood fiber play surfaces in two playground areas (~ 3,725 s.f. area).
Estimated Cost: \$2,794.00

09/15/11 Page 4 of 8

4.5 Sinks, Other than Lavatories

Not applicable.

5 COST ESTIMATE

5.1 Cost Estimate & Notes

■ Total facility cost estimate for recommended ADA modifications: \$10,771.00

09/15/11 Page 5 of 8

1 Access to the Facility	17-1	
1.1 Exterior Accessible Route	3,481.00	Install conc path to Swings, Bballcourt & blog
1.2 Parking	-	
1.3 Curb Ramps	2,500,00	Replace curb-cut @ Forest Ave.
1.4 Exterior Ramps	1,14600	Install short ramp into playground
1.5 Exterior Stairs	-	1 1/2
2 Services		
2.1 Building Entrances		
2.2 Interior Accessible Route	Te.	
2.3 Interior Ramps	-	
2.4 Interior Stairs		
2.5 Elevators		
2.6 Platform Lifts		
2.7 Doors	3.5	
2.8 Places of Assembly		
2.9 Seating and Tables	850.00	Add one access. Picnic table
2.10 Restaurant		
2.11 NOT USED		
2.12 Business and Mercantile	-	
2.13 Dressing and Fitting Rooms		
2.14 NOT USED		
2.15 NOT USED		
2.16 Libraries	-	
2.17 Storage		
3 Access to Public Amenities		
3.1 Drinking Fountains	YEL	
3.2 Toilet Rooms	-	
3.3 Signage	-	
3.4 Bathtubs and Showers		
4 Barrier Removal - Other		
4.1 Alarms		
4.2 Public Telephones	-	
4.3 Protruding Objects	-	
4.4 Work Areas Playgrounds	2,794.00	Supplement/Compact Wood Fiber play surface
4.5 Sinks, Other than Lavatories	-	The play sor lake
The state of the s		



This Page Intentionally Left Blank

09/15/11 Page 8 of 8